

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950

AIRSAFE AIRPORT EQUIPMENT CO LTD

ROOM 27AB DONGTAI BLDG

NO 309 TANGGU RD

SHANGHAI 200080 PRC

ORIGINAL ISSUE DATE: June 21, 2010

Recertification due: \_\_\_\_\_\_\_\_

An Activity Sponsored and Administered by Intertek

## AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

## CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-852 – Lights, Taxiway, Inpavement (AC 150/5345-46D)				
Manufacturer	Туре	Class	Style	Manufacturer's Catalog Number
Airsafe Airport Equipment Co. Ltd. No. 3 AnXin Rd, Xuhang	С	2	2	TCLM-08-S-048-GG (220); TCLM-08-S-048-YY (220); TCLM-08-S-048-GY (220)
Jiading District, Shanghai PRC	D	2	2	TCLM-08-C-048-G (220); TCLM-Ò8-Ć-048-Y (220) TCLM-08-C-048-GG (220); TCLM-08-C-048-YY (220)

- 1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
- 2. Product tested and Report issued by: Intertek
- (A) Report No: 3150398CRT-001

(B) Date of Report: 8/2008

Approved for Certification by:

11. Donno

Jeremy N. Downs, PE, Program Administrator

Date:June 21, 2010

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.